Wollumbin National Park
Summit Walking Track
Storm Damage 2013

Figure 1: Breakfast Creek Car Park Area covered by fallen trees.

Figure 2: Substantial tree down across Breakfast car park precinct. Note hanging and broken branches in canopy background which are major safety hazard.

Figure 3: Walking track covered in vines and debris including Giant stinging tree leaves at approx 10m.

Figure 4: Large tree across walking track at approx. 20m. Potential rerouting of track required due to sheer size and mass of tree.

Figure 5: Limbs, vines and trees obscure the walking track at approx. 300m.

Figure 6: Large tree-root ball uplifted and destroyed track surface at approx. 400m. Will require major relaying of track, establishment of drainage and rerouting to stable ground.

Figure 6: Tree fall uplifting track and damaging boardwalk at approx. 450m. Track requires rerouting, filling and construction of stabilising wall.

Figure 7: Large difficult to clear trees and vines across walking track at approximately 1km.

Figure 8: Track surface uplifted by tree fall and exposing bedrock at approx. 2 km. Note material to left of photo was original track surface above the bedrock upon which the NPWS staff member is standing. Depth of material can be seen in photo.

Figure 9: Large tree across track damaging safety rails at approx. 2.2 km. Difficult to move off track due to unstable surface, as noted by rocks, size and need to stabilise once removed.

Figure 10: several large trees down across track at approx. 3.1km. Representative of multiple sections of track.

Figure 11: Trees and debris obscure safe path at approx. 4 km. Note narrowness of track due to lost rock and soil.